



Model No. 398-4000 UpLift Bike Rack - 2 Bikes

8/30/2017 Page 1 of 7



220 Congress Park Dr. #215 Delray Beach, FL 33445 Ph: 800-695-3503

### **WARRANTY & TERMS**

**WARRANTY:** 5 Year Limited Warranty on Thermoplastic coated elements. The Park and Facilities Catalog guarantees all items for one full year to be free of defects in workmanship or materials when installed and maintained properly. We agree to repair or replace, any items determined to be defective. Items specifically not covered by this warranty include vandalism, man made or natural disasters, lack of maintenance, normal weathering or wear and tear due to public abuse.

Damages or loss in transit is the responsibility of the carrier, whether visible or concealed. It is the responsibility of the recipient to assure that the order is received complete. Before signing the delivery receipt, inspect the shipment immediately and completely. Note any damages or shortages on the bill of lading. Damage reports must be filed within 5 days. The Park and Facilities Catalog is NOT responsible for damages or loss in transit. Title to all goods passes to the customer at the time of shipment. The Park and Facilities Catalog will assist in filing claims if the freight arrangements were made by The Park and Facilities Catalog at your request.

**CANCELLATIONS AND RETURNS:** Cancellations are only accepted with approval of The Park and Facilities Catalog. No merchandise shall be returned without a Return Goods Authorization number which is issued by customer service. Any authorized merchandise must be carefully packed and received in saleable condition. A restocking charge of up to 25% will be applied to all returned goods when the error is not the fault of The Park and Facilities Catalog. All returns must be shipped freight prepaid.

#### **PRODUCT SPECIFICATIONS**

UpLift Bike Rack

Overall dimensions shall be 38-1/4" high x 16-3/8" wide x 23-3/4" deep. Framework shall be fabricated from 2" square tube. 11 gauge steel tube. Base is made from 1/4" steel plate. Wheel Stop shall be fabricated from 1/4" and 7 gauge steel plate. Lock loop shall be formed from 1/4" steel plate. Made to hold 2 bikes. Electrically MIG welded.

Coating: Oven fused functionalized polyethylene copolymer-based thermoplastic. Fluidized bed coating application with superior mechanical performance, impact resistance and UV-stability.


6/7/2017 Page 2 of 7



## **SAFETY WARNINGS & EQUIPMENT INSPECTION**


- Owners and installers please note these safety warnings and make use of this checklist on a regular basis.
- Follow installation instructions when erecting equipment.
- Ground surfaces around equipment should be restored as needed. Concrete footings should never be exposed. Surface depth should comply with ASTM and CPSC specifications.
- Check for and repair damage caused by wear or vandalism, a major factor in injury causing situations.
- All protruding bolts should be covered or cut off and finished smooth. Sharp edges on pipes should be capped or removed. Check for bent, broken, or severly worn pipe, and replace.
- All equipment should be free of rust and repainted whenever necessary to deter rusting.
- We provide our customers with layout sheets and installation instructions. Please keep on file the specifications sheet that contains the listing of every part used.
- Never add components not intended for use with this product.
- Regular maintenance is necessary in this and all park and recreational equipment to insure the safety of the user.
- Note: Proper maintenance of equipment requires regular tightening of all bolts, nuts, and setscrews.
- Note: Regular checking of all parts, castings, etc. should be made. If a part is broken or worn, it should be replaced immediatly.
- Check to be sure all fittings are tight and that bars and pipes do not move.
- Replace all worn S-hooks. S-hooks must be completely closed. Failure to close S-hooks can result in serious injury to the user.
  NEVER reuse S-hooks.
- Test for free movement of swing hanger and other moving attached parts.
- Check for worn chains and replace them.
- A soft resilient surface should be placed under all swings extending at least twice the height of the top rail both front and back.


9/19/2014 Page 3 of 7





8/30/2017 Page 4 of 7

# **TOOLS REQUIRED**









thepark


800-695-3503

www.theparkcatalog.com

8/30/2017 Page 5 of 7

## COMPONENTS

Attach the Left and Right Hand Wheel Stops to the Uplift Wheel Post using the specified hardware.



thepark

5/16" x 3" Machine Bolt (SS)

5/16" Kep Nut (SS)


5

33-05-0075 33-03-0012

800-695-3503

www.theparkcatalog.com

8/30/2017 Page 6 of 7



8/30/2017 Page 7 of 7